

- Glue this template to a piece of heavy paper such as a file folder.
- 2. Cut out the center of the circle, carefully cutting to the smallest diameter circle.
- 3. Cut an X across one of the mounting holes so you can put one of the mounting studs through the hole.
- 4. Place the template on the lathe spindle. Use the stud to align the template with one of the existing mounting holes.
- 5. Prick punch the other three mounting hole positions through the template.
- 6. Center punch the three new mounting hole positions.
- 7. Drill the three new mounting holes with a 1/8" pilot drill.
- Drill the three new mounting holes to size with a 17/64" drill.

Be sure that "Fit to page" is not checked when printing this document.