



Potentiometer switch is open in the full counter-clockwise (zero speed) position, closed otherwise.  
 Safety switch or E-stop goes between K3 and K4.

<b>LittleMachineShop.com</b>		
<small>© 2010 LittleMachineShop.com. All rights reserved.</small>		
<b>X1 Micro Mill</b>		
Revision 0	<b>4512</b>	Sheet 1 of 1